

HANES® MEN'S PERFECT-T® COTTON T-SHIRT

TA136C | TA136CFD | TA136CB

SIZE	CHEST	SLEEVES	LENGTH
S	18	16	28
M	20	16-3/4	29
L	22	17-1/2	31
XL	24	18-1/2	32
2XL	26	19-1/2	32-1/2
3XL	-	-	-
4XL	-	-	-
5XL	-	-	-

MEASURING TIPS

CHEST:

Measured across the chest one inch below armhole when laid flat.

SLEEVES:

Measured from center back neck, down shoulder to finished sleeve hem.

LENGTH:

Measured from high point of shoulder to finished hem at back.

PRODUCT MEASUREMENTS ARE IN INCHES